



R18 shouldn't be necessary, but experience with a CP2102 GPO interface to the debug port suggests we may need a stiff pulldown. Consider 10k in placeholder for experimentation since we have real boards in hand.