


R18 shouldn't be necessary, but experience with a CP2103 GPO interface to the debug port suggests we may need a stiff pullup. Consider 10k in placeholder for experimentation since we have read boards in hand.



### Open Avionics with Beacon