S3: Baff. - operation: 2 x AA battery or USB. - operation from USB\DC jack

P3: Jumper 2-8 enables Acc meter, 3-4: Disconnect fat cntrl power based device.

J101

P4: Jumper 7-8 reset

UCM B2U

P5: Jumpers 1-2 & 3-4

menu: pe removed when

menu: pe CC2430 dbgd. con.

S2-8 can be removed for

power down current f mes

P6. P7 all I/Os available

Header for remove

P9 jumpered when

enabled

CC2430 using P8