






2. top
3. bottom
4. outline
5. componentmask
6. soldermask
7. plated-drill
8. topsilk
9. bottomsilk
10. toppaste
11. topassembly
12. bottomassembly
13. fab





























There are 6 different drill sizes used in this layout, 64 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.015	43	YES
+	0.032	12	YES
x	0.038	4	YES
o	0.059	2	YES
□	0.059	1	YES
▽	0.098	2	YES

Title: (unknown) - Fabrication Drawing

Author: Bdale Garbee

Date: Wed 27 Jan 2010 11:23:34 PM GMT UTC

