


S3: Batt. - operation: 2 x AA batteries or USB. - operation from USB/DC jack
P3: Jumper 1-2: for ammeter, 3-4: Disconnects SW cntrl powered devices,
jumper 5-6 enables Acc meter self tst

P4: Jumper 7-8 resets
USB MCU

P5: Jumpers 1-2 & 3-4
must be removed when
using CC2430 debug con.
5-6 can be removed for
power down current mes
P6, P7 all I/Os available
Remember to remove
P5 jumpers when
debugging

CC2430 using P8



P2



B1



B2