

---

# Release Notes for Version 1.7

Version 1.7 includes support for our new TeleMini v3.0 flight computer and bug fixes in in the flight software for all our boards and ground station interfaces.

## 1. AltOS

### AltOS New Features

- Add support for TeleMini v3.0 boards.

### AltOS Fixes

- Fix interrupt priorities on STM32L processors. Run timer interrupt at lowest priority so that device interrupts get serviced first.

## 2. AltosUI and TeleGPS Applications

### AltosUI New Features

- Add support for TeleMini v3.0 hardware